



**FlexRay LLC.**  
**3751 New York Ave Suite #130**  
**Arlington, TX 76014**  
**Phone: 817-453-3539 Fax: 817-453-3542**

**Company and Plant location:** FLEX XRAY ARLINGTON, TX  
**Date:** 03-24-17  
**Product #:** 584931  
**Product Description:** SAMPLE PRODUCT  
**Project #:** 0324-17A

Pallet # 001	Pallet # 002	Pallet # 003	Pallet # 004	Pallet # 005
Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY
Bag/ Container Time: 13:12	Bag/ Container Time: 11:11	Bag/ Container Time: 10:05	Bag/ Container Time: 16:12	Bag/ Container Time: 05:07
Found Cont: METAL	Found Cont: PLASTIC	Found Cont: WOOD	Found Cont: GASKET	Found Cont: GLASS
Size (mm): 2.54mm X .89mm	Size (mm): 2.66mm X 1.97mm	Size (mm): 4.18mm X 2.66mm	Size (mm): 3.98mm X 2.38mm	Size (mm): 7.71mm X 4.70mm
Pallet # 006	Pallet # 007	Pallet # 008	Pallet # 009	Pallet # 009
Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY	Batch/Lot # FLEX-XRAY
Bag/ Container Time: 19:01	Bag/ Container Time: 20:01	Bag/ Container Time: 20:10	Bag/ Container Time: 22:00	Bag/ Container Time: 23:01
Found Cont: STONE	Found Cont: METAL	Found Cont: GASKET	Found Cont: BONE	Found Cont: HARD PLASTIC
Size (mm): 4.75mm X 3.30mm	Size (mm): 2.67mm X 1.43mm	Size (mm): 2.28mm X 1.72mm	Size (mm): 28.20 X 13.33mm	Size (mm): 3.85mm X 2.43mm

**Procedures: Reject Bag is pulled from the case. Product is inspected and the foreign object is removed. Foreign object is taped to this sheet and the corresponding pallet number and bag time stamp is recorded. The size and foreign object description is documented.**